
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>1</u> of <u>5</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/24/08
Test to be Performed:	Ground Condition:	Supervisor: GS
Smoke: _X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: S25EE 021	Test ID: 0994-662	Notifications Made: x (Residents, Fire, 311)

MAP 25EE Total Length = 624 LF



CITY OF BALTIMORE WET WEATHER CONSENT DECREE									
					_	<u>-</u>	Page 2	of5	
			ATER TESTING FORM				0 ===		
Sewershed: Jones Falls			Company: Savin Engineers				Date: 7/24/08		
Test to	be Performed:			Ground	Condition			Supervisor: G	S
Smoke	e: X Dye	d Water:		Dry: X	Dam	p: Wet	t:		
			_	,		· ———		Notifications Made: X	
Manho	le ID: S25EE 02	1		Test ID: 0994-662				(Residents, Fire, 311)	
Field	Sketch: (Show	all Manholes v	with Numl	bers, Blov	ver Placei	ment Location,	Sandbag or	Isolation	
	ons, Street Nam								
Defect		,		Source	,		Drainage	,	Photo
No.		Address		Туре	Location	Sector	Area	Severity	Number
	Alley Between		/Ivania	10	1	02	50	02	OB01-01
	Alley Between			16	1	02	25	03	OB02-01
	Alley Between			03	1	02	25	03	OB03-01
	577 Laurens St		iraina	02	08	01	50	02	OB04-01
	575 Laurens St			02	08	01	50	03	OB05-01
	Alley Between		/lvania	16	01	02	25	03	OB06-01
	Alloy Detween	Diditi & F Ciliis	rivariia	10	01	02	20	- 00	0000-01
				00000	(A TION	20050			
	Го т	1	0 1	OBSERV	ATION	CODES	Landen		
	Source Type	Location	Sector	Severity		Source Type	Location		
	Main Sewer	Paved Concrete	Public	No Smoke		MH Frame Seal	Non-Paved		
	Service Line	Paved Asphalt	Private	Trace		Storm Drain	Field/Woods		
03	Cleanout	Paved Other		Moderate		Catch Basin/Inlet			
	Downspout	Driveway		Major		Storm Manhole	Golf Course		
	Area Drain	Sidewalk				Storm Ditch	Other		
	Driveway Drain	Curb				Excavation			
	Stairwell Drain	Yard- Front			16	Other			
	Foundation Drain	Yard-Back							
09	Building Interior	Yard- Side		1	1	ĺ]		1

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>3</u> of <u>5</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/24/08
Test to be Performed:	Ground Condition:	Supervisor: GS
Smoke: _X Dyed Water:	Dry:X Damp: Wet:	
Manhole ID: S25EE 021	Test ID: 0994-662	Notifications Made: x (Residents, Fire, 311)



0994-662_OB01-01



0994-662_OB02-01

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>4</u> of <u>5</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/24/08
Test to be Performed:	Ground Condition:	Supervisor: GS
Smoke: _X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: S25EE 021	Test ID: 0994-662	Notifications Made: x (Residents, Fire, 311)



0994-662_OB03-01



0994-662 OB04-01

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>5</u> of <u>5</u>	
Sewershed: JONES FALLS SEWERSHED	Company: Savin Engineers	Date: 7/24/08
Test to be Performed:	Ground Condition:	Supervisor: GS
Smoke: _X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: S25EE 021	Test ID: 0994-662	Notifications Made: x (Residents, Fire, 311)



0994-662_OB05-01



0994-662_OB06-01